<b>Work Orde</b> April 6, 2010 4:	er ID 57426 00:17 PM											Page 1
Revision ID: Item Name:	D3836-041  Rib Assembly (Bash 06/04/2010 Sta			Accept		<b>ii</b>			<b>IIIII</b> s	-		
Required Date: Reference:		art Qty: 2.00 q'd Qty: 2.00				Cust Item I Customer:	D:	I				
Approvals:	Process Plan: QC:	- M	Date: 16-41-06  Date:	Tooling: SPC (Y/N):			ate:	-	F			
Sequence ID/ Work Center II	-	eration scription		Set Up/ Run Hours		Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. r Stamp
Draw Nbr	Revision	Nbr						1			/ <del>=</del>	
D3836	Rev A							:				
100 Large Fab	Larg	ge Fab Memo		0.00			and the second		2	6	0/10	.04.12
Large Fab			36-1 and D3836-3 rib as per d	lwg D3836								
		2- remove	identification markings	·	SAD	10-0	400	<b>P</b> .				
	÷	4- weld D3 to finish size	836-1 to D3836-3 and drill hoze as per dwg D3836	ole (3/16") using DTS				<del>'</del>			-	
I		A/R ER	327-3 spacer bushing as per c 316 S.S. Rod Batch: <u>iff</u>	79_								

QC9- Inspect visual per QSI004- Fusion Welds

Memo

Quality Control

0.00

0.00

D PD 10,04.13

Dart Aerospace Ltd
--------------------

	•									
W/O:			V	ORK ORDER CHANG	BES					
DATE	STEP	PROC	CEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							<del></del>			
							•			
Part No	:	PAR #:	_ Fault Ca	tegory:	_ NCR	: Yes N	lo <b>DQ</b>	<b>\</b> :	Date:	
		esolution:								
NCR:		W	ORK OR	DER NON-CONFORM	ANCE	(NCR)	V 100			
DATE	STEP	Description of NC	Corrective Action Section B			- Sign Verifica			Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
										-
								·		
				•	·			-		

## Work Order ID 57426

April 6, 2010 4:00:17 PM



Page 2

Item ID:

D3836-041

Accept



Setup Start

Stop



**Revision ID:** 

Item Name:

Rib Assembly (Basket Lid, LH)

**Start Date:** 

06/04/2010

Start Otv: 2.00

**Required Date: 12/04/2010** 

Rea'd Oty: 2.00



**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run

Start

Stop



QC:

Date:

**SPC (Y/N):** 

Set Un/

Run Hours

Draw

Number

Draw Rev.

Plan

Code

Date:

Accept Otv

Reject Reject Number

Insp. Stamp

Sequence ID/ Work Center ID

140

Quality Control

Operation Description

OC5- Inspect part completeness to step on W/O

0.00

8 (6/04/13

Qty

150



Packaging Packaging

Identify as per dwg & Stock Location:

Memo

Basket cell

0.00

0.00

160

**Quality Control** 

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

BS 10-4-13

Dart Aerospace	Ltd
----------------	-----

	•									
W/O:			W	ORK ORDER CH	ANGES					
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							<del></del>			
										,
Part No	:	PAR #:	Fault Cat	egory:	NCI	R: Yes	No DQA	۱:	_ Date: _	
	Re	esolution:	Dispositi	on:	`QA	N/C Clo	osed:		Date:	
NCR:			WORK ORI	DER NON-CONFO	RMANCE	(NCR	)			
DATE	STEP	Description of NC	Description of NC Corrective Action				Verific	ation	Approval	Approval
		Section A	Initial Chief Eng	Action Descrip Chief Eng	tion	Sign & Date	Section		Chief Eng	QC Inspector
,										-
					•					
										; :
							1	·		

April 6, 2010 4:00:21 PM

Work Order ID: 57426

D3836-041

Rib Assembly (Basket Lid, LH)

Comments:

Parent Item: Parent Item Name:

IPP Rev:A 08-12-01 new issue DD verified by:EC

Start Date: 06/04/2010

**Required Date: 12/04/2010** 

Start Oty: 2.00

Required Otv: 2.00

								-	Z.,	•	rioquii ou Qiji 2	.00
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2327-3  Spacer Bushing		Manufactured	No			100	Each	31.0000	2.0000		Cpl 10:	04.12
				Wareho	<u>ise</u>	Loc	<u>Qty</u>	Loc Code	•			
				Loca	tion				: 			
				Main Wa	rehouse							
				WA			31		:		-	
					55917		11		ć	2		
					57186		20				_	

M304TS0.750W.065

Purchased

No

100

562.8397 3.7491




10-04-09

Warehouse	Loc Oty	Loc Code	
Location			
Main Warehouse			
WA	562.8397		
111148	58		
113956	23.5		
114137	481.3397		3,7491

304 SQ Tube .75x.75x.065W


## **Dart Aerospace Ltd**

W/O:			V	VORK ORDER	CHANGES					
DATE	STEP	PRO	OCEDURE CI	HANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									·	
Part No	:	PAR #:	Fault Ca	itegory:	NO	CR: Yes	No DQ	<b>A</b> :	_ Date: _	
-	Reso	olution:	Disposit	tion:	Q.	A: N/C Cld	osed:		Date:	
NCR:		\	WORK OR	DER NON-CON	IFORMANC	E (NCR	)			
DATE	STEP	Description of NC	Corrective Action Section B Initial Action Description			Sign &	Verific		Approval	Approval
		Section A	Chief Eng	Chief E	ing	Date	Section	on C	Chief Eng	QC Inspector
										-
-										
			\$ 1 1							




## **Dart Aerospace Ltd**

W/O:			WC	ORK ORDER CHANG	ES			<u> </u>
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					,			·
Part No		PAR #:	Fault Cate	gory:	NCR: Yes 1	No DQA:	Date:	
		esolution:						
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCR)			
DATE	STEP	Description of NC	Description of NC Corrective Action			Verification	Approval	Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
								-
				·		·		
				-				



## **Dart Aerospace Ltd**

W/O:			V	VORK O	RDER CH	IANGES		<del></del>			**
DATE	STEP	PRO	OCEDURE CH	IANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	·									r	, e <b>3</b>
										No. 7	
Part No		PAR #:									
	Re	esolution:	Disposit	ion:		Q/	A: N/C CI	osed:		Date:	
NCR:			WORK OR	DER NO	N-CONF	DRMANC	E (NCR	)			
DATE	STEP	Description of NC	Description of NC Corrective Action					Verific	ation	Approval	Approval
	0.2.	Section A	Initial Chief Eng	A	ction Descri	ption 	Sign & Date	Secti	on C	Chief Eng	QC Inspector
											-
									-		
									:		
		·									



Dart	<b>Aeros</b>	pace	Ltd
------	--------------	------	-----

W/O:			N	ORK ORD	ER CHAN	IGES			-		
DATE	STEP	PRO	OCEDURE CH	ANGE		844	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					, , , , , , , , , , , , , , , , , , , ,						
			<del></del>			- <del></del>					
Part No	•	PAR #:	Fault Cat	tegory:		NC	R: Yes	No DQ	<b>A</b> :	_ Date: _	
	R	esolution:	Dispositi	on:		QA	: N/C CI	osed:		Date:	<del></del>
NCR:			WORK ORI	DER NON-	CONFORM	MANCE	(NCF	R)			
DATE	STEP	Description of NC	Initial	Corrective	Action Sen Description	ection B	Sign 8	Verific		Approval	Approval
		Section A	Chief Eng	ACTIO	Chief Eng		Date	Secti	on C	Chief Eng	QC Inspector
4			·								-
		. •	·				*				
		·		•.						,	
		·									<del></del>